
## **Engineering Change Management**





## Sustenance Engineering Support for Engineering changes

## Inputs:

Deviation Descriptions, Mark-up drawings, PPTs explaining the issues, ECO/ECR forms, etc.

- Process:
  - Problem Study
  - ✓ Impact Analysis- products/groups affected
  - ✓ Review of observations with site
  - ✓ Modify 3D models, update/create new drawing revisions
  - ✓ Complete ECO form and submit/notify to downstream functions like Purchasing, Planning, Quality etc
  - ✓ ERP system entry- BOM creation and update
- Result:
  - ✓ Updated Models & Drawings, ECO's submitted & PDM / ERP system update